

UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address COMMISSIONER FOR PATENTS FO Box 1430 Alexandria, Virginia 22313-1450 www.tepto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.
10/570,918	12/15/2006	Michael Helbig	12400-063	3834
757 7590 06/11/2009 BRINKS HOFER GILSON & LIONE			EXAMINER	
P.O. BOX 103	95		ENGLISH, JAMES A	
CHICAGO, IL 60610			ART UNIT	PAPER NUMBER
			3616	•
			MAIL DATE	DELIVERY MODE
			06/11/2009	PAPER

Please find below and/or attached an Office communication concerning this application or proceeding.

The time period for reply, if any, is set in the attached communication.

Advisory Action Before the Filing of an Appeal Brief

Application No.	Applicant(s)	
10/570,918	HELBIG ET AL.	
Examiner	Art Unit	
James English	3616	

- 8. 🔲 The affidavit or other evidence filed after a final action, but before or on the date of filing a Notice of Appeal will not be entered because applicant failed to provide a showing of good and sufficient reasons why the affidavit or other evidence is necessary and was not earlier presented. See 37 CFR 1.116(e).
- 9. The affidavit or other evidence filed after the date of filing a Notice of Appeal, but prior to the date of filing a brief, will not be entered because the affidavit or other evidence failed to overcome all rejections under appeal and/or appellant fails to provide a showing a good and sufficient reasons why it is necessary and was not earlier presented. See 37 CFR 41.33(d)(1).
- 10. The affidavit or other evidence is entered. An explanation of the status of the claims after entry is below or attached.
- REQUEST FOR RECONSIDERATION/OTHER
- 11. The request for reconsideration has been considered but does NOT place the application in condition for allowance because:
- 12. Note the attached Information Disclosure Statement(s). (PTO/SB/08) Paper No(s). 13. Other: .

/Ruth Ilan/ Primary Examiner, Art Unit 3616 Continuation of 3. NOTE: The proposed change to claim 1, in part being "the perforated section having one or more perforations formed completely through a part of the main housing structure that extends away from the housing cover adjacent to the inner side", raises new issues that would require further consideration and/or search.